

Stuck Flow Switch

- 1) Flow inside chiller is measured with a flow switch
- 2) Flow switch got stuck in the past. Symptom: "Low Flow" light on the chiller control panel. Could be restarted by hitting its controller box (located on the chiller) with a wrench
- 3) Defective ISL chiller flow switch exchanged during 2006 shutdown, but problem re-occurred later. Both ISL & SVX flow switches have been changed again in 2007.